



Certificate

Page : 1/2

Certificate of constancy of performance for products.

In compliance with the Regulation 305/2011/UE of the European Parliament and of the Council of 9 March 2011 (Construction Products Regulation or CPR)

Delivered by :

Certification body : **AFNOR CERTIFICATION**
Identification number : **0333**
Address : **11, RUE FRANCIS DE PRESSENSE
FR-93571 LA PLAINE SAINT-DENIS CEDEX**

Issued to :

Manufacturer : **SAVIO THESAN SPA**
Address : **VIA TORINO 25
IT 10050 CHIUUSA SAN MICHEL (TO)**

Manufacturing site(s) : **NUOVI PRODOTTI KFT - PETOFI UT 3 - HU- 3102 SALGOTARJAN**

Description of the product(s) : see next page(s)

AFNOR Certification attests that the provisions concerning the assessment and verification of constancy of performance and the performances described in annex ZA of the standard EN1125:2008 under system 1 and that the products fulfills the provisions described in annex ZA of the standard EN1125:2008.

Certificate number : CPD40-240012

Conditions and certificate validity period : this certificate was first issued on 03/12/2010.

Unless suspended or withdrawn, this certificate remains valid as long as the conditions laid down in the harmonized technical specifications or the manufacturing conditions in the factory or the factory production control itself are not significantly modified.

This certificate cancels and replaces any previous certificate.

Date of issue of the certificate : 03/06/2019



SignatureFournisseur

Franck LEBEUGLE
Managing Director of AFNOR Certification

CERTI F 1399.2 11/2014



Certificate

Page : 2/2

Certificate n° CPD40-240012 issued on 03/06/2019

Description of the product(s) :

Identification of product(s)	Accessory reference(s)	Standard(s)	Classification(s) according to the standard	Intended use(s)
BERNINI 6000.1-1200 6000.2-1200 6000.3-1200	6000.701, 6000.702, 6000.703, 6000.720, 6000.721, 6000.730, 6000.735, 6000.740, 6000.802, 6000.803, 6000.804, 6000.805, 6000.810, 6000.820, 6000.830, 6000.842, 6000.B/1500	EN1125:2008	3 7 7 0 1 4 2 2 A A	Serviceability on door unit on evacuation routes