



Certificate

Page : 1/2

Certificate of constancy of performance for products.

In compliance with the Regulation 305/2011/UE of the European Parliament and of the Council of 9 March 2011 (Construction Products Regulation or CPR)

Delivered by :

Certification body : **AFNOR CERTIFICATION**
Identification number : **0333**
Address : **11, RUE FRANCIS DE PRESSENSE
FR-93571 LA PLAINE SAINT-DENIS CEDEX**

Issued to :

Manufacturer : **SAVIO THESAN SPA**
Address : **VIA TORINO 25
IT- 10050 CHIUSA SAN MICHELE (TO)**

Manufacturing site(s) : SAVIO THESAN SPA - VIA TORINO 25 - IT- 10050 CHIUSA SAN MICHELE (TO)

Description of the product(s) : see next page(s)

AFNOR Certification attests that the provisions concerning the assessment and verification of constancy of performance and the performances described in annex ZA of the standard EN1935:2002+AC:2003 under system 1 and that the products fulfills the provisions described in annex ZA of the standard EN1935:2002+AC:2003.

Certificate number : 0333-CPR-140013

Conditions and certificate validity period : this certificate was first issued on 28/02/2003.

Unless suspended or withdrawn, this certificate remains valid as long as the conditions laid down in the harmonized technical specifications or the manufacturing conditions in the factory or the factory production control itself are not significantly modified.

This certificate cancels and replaces any previous certificate.

Date of issue of the certificate : 03/06/2019



SignatureFournisseur

Franck LEBEUGLE
Managing Director of AFNOR Certification

CERTI F 1399.2 11/2014

Certificate n° 0333-CPR-140013 issued on 03/06/2019

Description of the product(s) :

Identification of product(s)	Standard(s)	Classification(s) according to the standard	Intended use(s)
1148	EN1935:2002+AC:2003	3 7 4 0 1 4 0 11	Serviceability on door unit on evacuation routes
1145/53	EN1935:2002+AC:2003	3 7 4 0 1 4 0 11	Serviceability on door unit on evacuation routes
1145/60MR	EN1935:2002+AC:2003	2 7 3 0 1 4 0 10	Serviceability on door unit on evacuation routes
1144/67B 1145/60 1145/67 1146/59 1146/62.5 1146/67 1146.2/62	EN1935:2002+AC:2003	4 7 7 0 1 4 0 14	Serviceability on door unit on evacuation routes
1145/79 1146/74.5 1146/78	EN1935:2002+AC:2003	4 7 6 0 1 4 0 13	Serviceability on door unit on evacuation routes
1145/93 1145/93SM 1145/86 1146/84 1146/89 1146/92	EN1935:2002+AC:2003	4 7 5 0 1 4 0 12	Serviceability on door unit on evacuation routes
1148.3	EN1935:2002+AC:2003	4 7 5 0 1 4 1 12	Serviceability on door unit on evacuation routes
1143.36	EN1935:2002+AC:2003	4 7 6 0 1 4 1 13	Serviceability on door unit on evacuation routes
1145.3/60 1145.3/67 1146.3/59 1146.3/62.5 1146.3/67 1146.23/62	EN1935:2002+AC:2003	4 7 7 0 1 4 1 14	Serviceability on door unit on evacuation routes
1146.3/74.5 1146.3/78 1145.3/79	EN1935:2002+AC:2003	4 7 6 0 1 4 1 13	Serviceability on door unit on evacuation routes
1145.3/93 1146.3/84 1146.3/89 1146.3/92	EN1935:2002+AC:2003	4 7 5 0 1 4 1 12	Serviceability on door unit on evacuation routes